

NEW NEWS

NO. 293

FEBRUARY, 10, 2020

Dear Valued 555 Customers:

SANKEI INDUSTRY CO., LTD.
305 Takano, Ritto, Shiga, 520-3045, JAPAN
E-mail : info@sankei-555.co.jp

New Products

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
13	SE-T071R	45460-59045 ①	CELSIOR	UCF30	00-	OUT R	30pcs	BEGINNING OF APRIL
13	SE-T071L	45470-59045 ①	CELSIOR	UCF30	00-	OUT L	30pcs	BEGINNING OF APRIL
39	SE-H651	53540-SJC-A01 ①	USA ODYSSEY	RL5	11-	OUT R/L	50pcs	BEGINNING OF APRIL
39	SE-H791R	53540-T1W-A01 ①	USA CR-V	RM	15-	OUT R	50pcs	BEGINNING OF APRIL
39	SE-H791L	53560-T1W-A01 ①	USA CR-V	RM	15-	OUT L	50pcs	BEGINNING OF APRIL
73	SR-M090	K123-32-240 ①	CX-5	KFEP	16-	R/L	40pcs	BEGINNING OF APRIL
80	SR-H800	53610-TP6-A62 ①	CROSS TOUR	TF	13-	R/L	40pcs	BEGINNING OF APRIL
80	SR-H800-M	53610-TP6-A62-M ①	CROSS TOUR	TF	13-	R/L with 1 claw washer	40pcs	BEGINNING OF APRIL
84	SR-6760	34140-AC000 ①	BAJA	BT	03-06	R/L	30pcs	BEGINNING OF APRIL
84	SR-6760-M	34140-AC000-M ①	BAJA	BT	03-06	R/L with 1 claw washer	30pcs	BEGINNING OF APRIL

**THE BEST QUALITY PARTS
 FROM THE MOST ADVANCED MFG. FACILITIES**

*Tie Rod End. Side Rod Assy. Ball Joint. Idler Arm.
 Pitman Arm. Center Link. Drag Link. Inner Arm Shaft.*



ISO9001

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	MODEL	YEAR	POSITION	/CARTON	START (DELIVERY)
151	SL-3880-B	48820-0K010-B ①	HILUX VIGO KIJANG INNOVA HILUX	KUN15 KUN40, TGN4# KUN10, KUN15, KUN16, GGN15, LAN15, TGN1#	04/8- 04- 04-06	FRONT R/L with Bush Kit	80pcs	BEGINNING OF APRIL
155	SL-A300	48820-36022 ①	COASTER	XZB60	17-	FRONT R/L	30pcs	BEGINNING OF APRIL
155	SL-A300-M	48820-36022-M ①	COASTER	XZB60	17-	FRONT R/L with 2 nuts	30pcs	BEGINNING OF APRIL
168	SL-N145	56261-CK000 ①	QUEST	V42	04-	REAR R/L	100pcs	BEGINNING OF APRIL
168	SL-N145-M	56261-CK000-M ①	QUEST	V42	04-	REAR R/L with 2 nuts	100pcs	BEGINNING OF APRIL
195	SL-6770R	20420-FL020 ①	XV	GT7	17-	FRONT R	30pcs	BEGINNING OF APRIL
195	SL-6770R-M	20420-FL020-M ①	XV	GT7	17-	FRONT R with 2 nuts	30pcs	BEGINNING OF APRIL
195	SL-6770L	20420-FL030 ①	XV	GT7	17-	FRONT L	30pcs	BEGINNING OF APRIL
195	SL-6770L-M	20420-FL030-M ①	XV	GT7	17-	FRONT L with 2 nuts	30pcs	BEGINNING OF APRIL

Note 1: New items are not listed on the back "555" catalogues (~Vol. 18).

Note 2: START (DELIVERY) indicates available date.

Please refer to "Additional Applications" and "Product information" on the following pages.

Additional Applications


Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
7	SE-2931		PREMIO ※	ZRT265. . CBU ※	10- ※	OUT R/L
24	SE-N331R		SUNNY ※ ALMERA ※	N17K ※ N17K ※	11- ※ 11- ※	OUT R
24	SE-N331L		SUNNY ※ ALMERA ※	N17K ※ N17K ※	11- ※ 11- ※	OUT L
24	SE-N341R	D8520-3SG1A ※	SENTRA ※	B17U ※	12- ※	OUT R
24	SE-N341L	D8640-3SG1A ※	SENTRA ※	B17U ※	12- ※	OUT L
59	SR-T470		ALPHARD	ANH10, MNH10 ※	05- ※	R/L
59	SR-T470-M		ALPHARD	ANH10, MNH10 ※	05- ※	R/L
60	SR-T720		VITZ ※	NCP131, NSP130. . U. . CBU ※ KSP130, NSP130. . (F, JEWL) . . CBU ※	12- ※	R/L
102	SA-T222R	48068-42051-1 ※ For ARM ASSY 48068-42051 ※				LOW R
102	SA-T222L	48069-42051-1 ※ For ARM ASSY 48069-42051 ※				LOW L
103	SB-T552	48068-EZ200-1 ※ 48069-EZ200-1 ※ 48068-EZ390-1 ※ 48069-EZ390-1 ※ For ARM ASSY 48068-EZ200 ※ 48069-EZ200 ※ 48068-EZ390 ※ 48069-EZ390 ※	AVANZA RUSH ※	F653 ※ F654 ※ F800 ※	15- ※ 15- ※ 18- ※	LOW R/L
112	SB-4982	54500-1LA0D-1 ※ 54501-1LA0D-1 ※ For ARM ASSY 54500-1LA0D ※ 54501-1LA0D ※	ARMADA	Y62J ※	16- ※	UP R/L
113	SB-N252	54501-4JA0A-1 ※ 54500-4JA0A-1 ※ 54501-4JA2C-1 ※ 54500-4JA2C-1 ※ For ARM ASSY 54501-4JA0A ※ 54500-4JA0A ※ 54501-4JA2C ※ 54500-4JA2C ※	NP300 NAVARA ※	D23T ※ D23T ※	14- ※ 17- ※	LOW R/L
119	SB-7841	4010A137 ※	L200 ※	KB4T	07- ※	FRONT UP
155	SL-A110		JPN TAXI ※	NIP10 ※	17- ※	FRONT R/L
155	SL-A110-M		JPN TAXI ※	NIP10 ※	17- ※	FRONT R/L with 2 nuts
156	SL-T020	48820-OD010 ※	YARIS ※	KSP90 ※	05- ※	FRONT R/L

Catalogue page	555 NO.	O. E. M. NO.	CAR NAME	M O D E L	YEAR	POSITION
156	SL-T020-M	48820-0D010-M ※	YARIS ※	KSP90 ※	05- ※	FRONT R/L with 2 nuts
169	SL-N220	54618-9AM1A ※	NV200 ※	M20X ※	14- ※	FRONT R/L
169	SL-N220-M	54618-9AM1A-M ※	NV200 ※	M20X ※	14- ※	FRONT R/L with 2 nuts
173	SL-N830R	54618-3JA0C ※	ALTIMA ※	L33 ※	12- ※	FRONT R
173	SL-N830R-M	54618-3JA0C-M ※	ALTIMA ※	L33 ※	12- ※	FRONT R with 2 nuts
173	SL-N830L	54668-3JA0C ※	ALTIMA ※	L33 ※	12- ※	FRONT L
173	SL-N830L-M	54668-3JA0C-M ※	ALTIMA ※	L33 ※	12- ※	FRONT L with 2 nuts
176	SL-7950R	4056A193 ※	L200 ※	KB4T	07- ※	FRONT R
176	SL-7950R-M	4056A193-M ※	L200 ※	KB4T	07- ※	FRONT R with 2 nuts
176	SL-7950L	4056A192 ※	L200 ※	KB4T	07- ※	FRONT L
176	SL-7950L-M	4056A192-M ※	L200 ※	KB4T	07- ※	FRONT L with 2 nuts
190	SL-H470R		HR-V ※		16- ※	FRONT R
190	SL-H470R-M		HR-V ※		16- ※	FRONT R with 2 nuts
190	SL-H470L		HR-V ※		16- ※	FRONT L
190	SL-H470L-M		HR-V ※		16- ※	FRONT L with 2 nuts
196	SL-S170		SOLIO ※	MA36S	15- ※	FRONT R/L
196	SL-S170-M		SOLIO ※	MA36S	15- ※	FRONT R/L with 2 nuts

※ marks are additional information which are not on 555 catalogs until Vol. 18

Product Information

Please be announced that Sankei will have the design change of some existing stabilizer links as below.



The following 555#s will have this design change. The change will be implemented from April shipment upon running out of the stock of current version for each part#.

SLK-8010	SLK-8150L	SLK-8236L	SLK-8470
SLK-8030	SLK-8155R	SLK-8240R	SLK-8480
SLK-8040	SLK-8155L	SLK-8240L	SLK-8500R
SLK-8045	SLK-8160R	SLK-8250R	SLK-8500L
SLK-8060R	SLK-8160L	SLK-8250L	SLK-8510R
SLK-8060L	SLK-8170R	SLK-8260R	SLK-8510L
SLK-8065	SLK-8170L	SLK-8260L	SLK-8520R
SLK-8070	SLK-8175R	SLK-8265	SLK-8520L
SLK-8080R	SLK-8175L	SLK-8270	SLK-8530
SLK-8080L	SLK-8180R	SLK-8275	SLK-8545
SLK-8090	SLK-8180L	SLK-8280	SLK-8550
SLK-8095	SLK-8190R	SLK-8290R	SLK-8555
SLK-8100	SLK-8190L	SLK-8290L	SLK-8560R
SLK-8105	SLK-8200R	SLK-8295	SLK-8560L
SLK-8110	SLK-8200L	SLK-8300R	SLK-8580R
SLK-8115	SLK-8210	SLK-8300L	SLK-8580L
SLK-8120R	SLK-8211	SLK-8320	SLK-8620
SLK-8120L	SLK-8220R	SLK-8415	SLK-8670R
SLK-8130	SLK-8220L	SLK-8425	SLK-8670L
SLK-8135	SLK-8230	SLK-8435	SLK-8710
SLK-8140	SLK-8235	SLK-8460R	SLK-8755R
SLK-8150R	SLK-8236R	SLK-8460L	SLK-8755L